



To: Ammunition Customers
From: Ben Frank
CC: Mike Bokermann, Ed Harris, Matt Campbell, Todd Tittle, Jason Gilbertson
Date: August 20, 2021
Re: Corrected Lot Number on Winchester 9mm Luger Recall

Please reference previous Winchester, Browning and Herter's Recall letter sent on June 21, 2021.

Winchester has identified a typographical error in one Winchester lot number listed on the recall notice and is resending this notice to make the correction. Lot Number SC10LD12 has been corrected to Lot Number SD10LD12. There is no change to the Herter's or Browning lists of Lot Numbers.

Winchester has initiated a voluntary recall of 9mm Luger 115 grain Full Metal Jacket & 115 grain Jacketed Hollow Point. The following Winchester symbols and date codes are covered by this recall:

Symbols: Q4172, RED9, USA9JHP, USA9MMVP, USA9W, WW9B

Lot Numbers for all affected symbols:

**SC03LD44, SC03LD45, SC03LD46, SC03LD47
SC13LD1, SC13LD6, SC13LD18, SC13LD44, SC13LD45, SC13LD46, SC13LD47
SC52LD44, SC52LD45, SC52LD46, SC52LD47
SC62LD44, SC62LD45, SC62LD46, SC62LD47
SC72LD44, SC72LD45, SC72LD46, SC72LD47
SC92LD44, SC92LD45, SC92LD46, SC92LD47
SD10LD1, SD10LD3, SD10LD6, **SD10LD12 ***, SD10LD18, SD10LD46, SD10LD47
SD50LD1, SD50LD3, SD50LD6, SD50LD11, SD50LD12, SD50LD18, SD50LD46, SD50LD47
SD60LD1, SD60LD3, SD60LD6, SD60LD11, SD60LD12, SD60LD18
SD70LD1, SD70LD3, SD70LD6, SD70LD11, SD70LD12, SD70LD18
SD80LD1, SD80LD3, SD80LD6, SD80LD11, SD80LD12, SD80LD18**

*** Note: Lot Number SC10LD12 has been corrected to Lot Number SD10LD12**

Additionally, there are two symbols not under the Winchester brand that are affected - Herter's 9mm Luger 115 grain Full Metal Jacket in a 50-round box and a Browning 9mm Luger 115 grain Full Metal Jacket in a 50-round box.

Herter's Symbol: HRT9A

Lot Numbers: SC13LD44, SC13LD45, SD10LD44, SD10LD45

Browning Symbol: B191800092

Lot Numbers: SC13LD20, SD10LD20

Note: If ammunition was purchased before March 25, 2021, it is NOT subject to the recall.

Winchester has determined the above lots of 9mm Luger 115 FMJ and JHP ammunition may contain propellant that does not properly ignite and burn when the cartridge is fired. Ammunition containing propellant that does not properly ignite and burn may result in a bullet remaining in the barrel (i.e., a bullet-in-bore obstruction). Firing a subsequent bullet into the bore obstruction could cause firearm damage, rendering the firearm inoperable and subjecting the shooter and bystanders to a risk of serious personal injury.

We request that you post the attached, corrected recall notice in your store and on your website to ensure this notice reaches as many of your customers as possible.

We have identified all suspect lot numbers and are implementing a nation-wide recall.

This recall has been posted on the Winchester and Browning Ammunition websites and we have acquired ad space in upcoming print and electronic media publications.

We request that you audit any material you have in-stock, looking for the subject Symbols and Lot Numbers. If you have any of these Symbols and Lot Numbers, please isolate the material at your facility and contact your Winchester Sales Representative or call our hotline below for further instruction.

Please review the recall notice on the Winchester website (www.winchester.com). Any questions may be directed to our hotline at 1-844-653-8358 or through our product support link <https://winchester.com/Support/Customers/Product-Support>.

Thank you for your attention in this matter,

Ben Frank
Manager, Product Service
Winchester Ammunition
618.258.3535
bnfrank@olin.com