

SAFETY RECALL

YETI Recalls Soft Coolers and Gear Case Due to Magnet Ingestion Hazard



The magnet-lined closures of the Hopper M20 Soft Backpack Cooler, the Hopper M30 Soft Cooler (both the 1.0 and 2.0 versions) and the SideKick Dry Gear Case can fail and result in detached magnets, which poses a risk of serious injury or death if ingested.



Hopper M30 1.0



Hopper M30 2.0



Hopper M20



SideKick Dry

Sold between March 2018 and January 2023 for \$450 CAD (Hopper M20 Soft Backpack Cooler), \$400 CAD (Hopper 1.0 Soft Cooler); \$480 CAD (Hopper 2.0 M30 Soft Cooler) and \$65 CAD (SideKick Dry Gear Case).

Consumers should immediately stop using the recalled products listed above, visit www.YETI.ca and click on “Product Recall” at the bottom of the page for information on how to return the recalled product for a free replacement or gift card as shown below:

- Sidekick Dry: \$65 CAD MAP
 - Daytrip Bag/Box (\$100 CAD MAP) OR \$90 CAD Gift Card
- M20: \$450 CAD MAP
 - Tundra 45 (\$425 CAD MAP) + \$100 CAD Gift Card OR \$500 CAD Gift Card
- M30 1.0: \$400 CAD MAP
 - Flip 18 (\$400 CAD MAP) + \$75 CAD Gift Card OR \$450 CAD Gift Card
- M30 2.0: \$480 CAD MAP
 - Tundra 65 (\$500 CAD MAP) + \$75 CAD Gift Card OR \$550 CAD Gift Card

Customers can also contact YETI toll-free at 1-833-444-3151 from 7:00 AM to 7:00 PM CT, or email ProductRecall@yeti.com for more information.